

America's Premier Inspection Service

INSPECTION REPORT

Jason Rosh Baker TREC #23659 National Property Inspections - Central Texas

2400 Jackson Street Client: Michael Jordan Agent: Matthew McLeod - The McLeod Company

> Inspection Date: 2-8-2021 Built: 2011 Size: 4992 Weather: Cloudy 52 degrees Fahrenheit



Jason Baker, TREC Lic. #23659 Jason.Baker@npiinspect.com 254-523-3857

Like us on Facebook! @NPIWaco

G Review us on Google: www.g.page/NPIWaco

TrussWorthy Property Inspections, Inc.	dba
National Property Inspections	

PROPERTY INSPECTION REPORT		
Prepared For:	Michael Jordan	
	(Name of Client)	
Concerning:	2400 Jackson Street, Gary, TX 76633	
u –	(Address or Other Identification of Inspected Prop	perty)
By:	Jason Rosh Baker, TREC #23659	2-8-2021
	(Name and License Number of Inspector)	(Date)

PURPOSE, LIMITATIONS AND INSPECTOR / CLIENT RESPONSIBILITIES

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions. If any item or comment is unclear, you should ask the inspector to clarify the findings. It is important that you carefully read ALL of this information.

This inspection is subject to the rules ("Rules") of the Texas Real Estate Commission ("TREC"), which can be found at www.trec.texas.gov.

The TREC Standards of Practice (Sections 535.227-535.233 of the Rules) are the minimum standards for inspections by TREC licensed inspectors. An inspection addresses only those components and conditions that are present, visible, and accessible at the time of the inspection. While there may be other parts, components or systems present, only those items specifically noted as being inspected were inspected. The inspector is NOT required to turn on decommissioned equipment, systems, utility services or apply an open flame or light a pilot to operate any appliance. The inspector is NOT required to climb over obstacles, move furnishings or stored items. The inspection report may address issues that are code-based or may refer to a particular code; however, this is NOT a code compliance inspection and does NOT verify compliance with manufacturer's installation instructions. The inspection does NOT imply insurability or warrantability of the structure or its components. Although some safety issues may be addressed in this report, this inspection is NOT a safety/code inspection, and the inspector is NOT required to identify all potential hazards.

In this report, the inspector shall indicate, by checking the appropriate boxes on the form, whether each item was inspected, not inspected, not present or deficient and explain the findings in the corresponding section in the body of the report form. The inspector must check the Deficient (D) box if a condition exists that adversely and materially affects the performance of a system or component or constitutes a hazard to life, limb or property as specified by the TREC Standards of Practice. General deficiencies include inoperability, material distress, water penetration, damage, deterioration, missing components, and unsuitable installation. Comments may be provided by the inspector whether or not an item is deemed deficient. The inspector is not required to prioritize or emphasize the importance of one deficiency over another.

Some items reported may be considered life-safety upgrades to the property. For more information, refer to Texas Real Estate Consumer Notice Concerning Recognized Hazards or Deficiencies below.

THIS PROPERTY INSPECTION IS NOT A TECHNICALLY EXHAUSTIVE INSPECTION OF THE STRUCTURE, SYSTEMS OR COMPONENTS. The inspection may not reveal all deficiencies. A real estate inspection helps to reduce some of the risk involved in purchasing a home, but it cannot eliminate these risks, nor can the inspection anticipate future events or changes in performance due to changes in use or occupancy. It is recommended that you obtain as much information as is available about this property, including any seller's disclosures, previous inspection reports, engineering reports, building/remodeling permits, and reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers. You should also attempt to determine whether repairs, renovation, remodeling, additions, or other such activities have taken place at this property. It is not the inspector's responsibility to confirm that information obtained from these sources is complete or accurate or that this inspection is consistent with the opinions expressed in previous or future reports.

ITEMS IDENTIFIED IN THE REPORT DO NOT OBLIGATE ANY PARTY TO MAKE REPAIRS OR TAKE OTHER ACTIONS, NOR IS THE PURCHASER REQUIRED TO REQUEST THAT THE SELLER TAKE ANY ACTION. When a deficiency is reported, it is the client's responsibility to obtain further evaluations and/or cost estimates from qualified service professionals. Any such follow-up should take place prior to the expiration of any time limitations such as option periods.

Promulgated by the Texas Real Estate Commission (TREC) P.O. Box 12188, Austin, TX 78711-2188 (512) 936-3000 (http://www.trec.texas.gov).

REI 7-5 (05/4/2015)

Page 1 of 30

TrussWorthy Property Inspections, Inc. dba National Property Inspections

Evaluations by qualified tradesmen may lead to the discovery of additional deficiencies which may involve additional repair costs. Failure to address deficiencies or comments noted in this report may lead to further damage of the structure or systems and add to the original repair costs. The inspector is not required to provide follow-up services to verify that proper repairs have been made.

Property conditions change with time and use. For example, mechanical devices can fail at any time, plumbing gaskets and seals may crack if the appliance or plumbing fixture is not used often, roof leaks can occur at any time regardless of the apparent condition of the roof, and the performance of the structure and the systems may change due to changes in use or occupancy, effects of weather, etc. These changes or repairs made to the structure after the inspection may render information contained herein obsolete or invalid. This report is provided for the specific benefit of the client named above and is based on observations at the time of the inspection. If you did not hire the inspector yourself, reliance on this report may provide incomplete or outdated information. Repairs, professional opinions or additional inspection reports may affect the meaning of the information in this report. It is recommended that you hire a licensed inspector to perform an inspection to meet your specific needs and to provide you with current information concerning this property.

TEXAS REAL ESTATE CONSUMER NOTICE CONCERNING HAZARDS OR DEFICIENCIES

Each year, Texans sustain property damage and are injured by accidents in the home. While some accidents may not be avoidable, many other accidents, injuries, and deaths may be avoided through the identification and repair of certain hazardous conditions. Examples of such hazards include:

- malfunctioning, improperly installed, or missing ground fault circuit protection (GFCI) devices for electrical
- receptacles in garages, bathrooms, kitchens, and exterior areas;
- malfunctioning arc fault protection (AFCI) devices;
- ordinary glass in locations where modern construction techniques call for safety glass;
- malfunctioning or lack of fire safety features such as smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- malfunctioning carbon monoxide alarms;
- excessive spacing between balusters on stairways and porches;
- improperly installed appliances;
- improperly installed or defective safety devices;
- lack of electrical bonding and grounding; and
- lack of bonding on gas piping, including corrugated stainless steel tubing (CSST).

To ensure that consumers are informed of hazards such as these, the Texas Real Estate Commission (TREC) has adopted Standards of Practice requiring licensed inspectors to report these conditions as "Deficient" when performing an inspection for a buyer or seller, if they can be reasonably determined.


These conditions may not have violated building codes or common practices at the time of the construction of the home, or they may have been "grandfathered" because they were present prior to the adoption of codes prohibiting such conditions. While the TREC Standards of Practice do not require inspectors to perform a code compliance inspection, TREC considers the potential for injury or property loss from the hazards addressed in the Standards of Practice to be significant enough to warrant this notice.

Contract forms developed by TREC for use by its real estate licensees also inform the buyer of the right to have the home inspected and can provide an option clause permitting the buyer to terminate the contract within a specified time. Neither the Standards of Practice nor the TREC contract forms require a seller to remedy conditions revealed by an inspection. The decision to correct a hazard or any deficiency identified in an inspection report is left to the parties to the contract for the sale or purchase of the home.

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENT WITH THE STANDARD FORM, IS NOT REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTUAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT REGULATE CONTRACTUAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTUAL TERM CONTAINED IN THIS SECTION OR ANY ATTACHMENTS, CONSULT AN ATTORNEY.

ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

REI 7-5 (05/4/2015)





NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D



Roof

Roof



Roof

Roof



NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D



Attic





Attic

Attic





Attic






REI 7-5 (05/4/2015)





Cracked glass. Garage

Rusted lintels on some windows, not painted. Left side





NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D



Front porch

Back porch

II. ELECTRICAL SYSTEMS

x | | |

A. Service Entrance and Panels


Panel Locations: Main electrical is located in garage., Sub panel is located in garage Materials and Amp Rating: Copper wiring, 200 amp Comments:



Main and subpanel

Main panel wires

TrussWorthy P National Propert	roperty Inspections, Inc. db y Inspections	a	2400 Jackson Street, Gary, TX
I=Inspected	NI=Not Inspected		D=Deficient
I NI NP			
		nnected Devices, and F	Fixtures
	Type of Wiring: Coppe Comments:	er wiring	
	B.1. Missing switch co	over.	
	First	sing switch cover. Attic	
		III. HVAC	
x	A. Heating Equipment		
	Type of Systems: <mark>Hea</mark> Energy Sources: Elec Comments:	<mark>it pump</mark> s tric	
	A.1. Heating units per	formed as intended at t	he time of inspection.



D=Deficient NP=Not Present I=Inspected NI=Not Inspected NI NP D Condensers 1 and 2 Missing dead front cover. Condenser service disconnect SERIAL 4811E07669 25HBC548A0030010 PROD SERIAL 4511E11615 25HBC548A300 MODEL PROD 25HBC54BA0030010 INDEL 25HBC54BA0030010 INETERING TXU 67 PISTON PEUTCE INDOOR 01700R FACTORY CHARGED R410A A 35 KG 67 PISTON HETERING TXU DEVICE INDOOR OUTDOOR
 NEWICE
 INDOOR
 OF
 OUTDOOR

 ACTORY CHARGED
 R410A
 R410A

 GLOBY CHARGED
 R410A
 35 kg

 INDOOR TWO SUB COLLING
 13 "FF

 DURR SUPPLY
 208-230 VOLTS AC

 PR
 B
 60 r.2

 SISTREF COLTAGE AT UNIT
 253 max
 197 mT

 SUTIRAL FOR OUTBOOR USE
 208/230 VOLTS AC
 17.9 LA

 Fram NOTOR
 209/230 VOLTS AC
 11.7.9 LA

 Fram NOTOR
 209/230 VOLTS AC
 1.4 mb

 Fram NOTOR
 2.0 mb
 1.2 mb

 Fram NOTOR
 Fram NOTOR
 2.0 mb

 Fram NOTOR
 Fram NOTOR
 2.0 mb

 Fr R410A 9.60 LBS 4.35 KG INDOOR TXV SUB COOLING 13 °F POWER SUPPLY 208-230 VOLTS AC 1 PH 60 PERMISSIBLE VOLTAGE AT UNIT HZ 253 MAX 197 MIN SUITABLE FOR OUTDOOR USE
 COR
 208/230
 VOLTS AC

 1
 PH
 60
 HZ

 21.8
 RLA
 117.0
 LRA

 OR
 208/230
 VOLTS AC
OMPRESSOR 208/230 450 PSI 3103 250 PSI 1724 K DESIGN/WORK ING PRESS 60 1.2 GAGE FLA
 700
 psic
 4826 ki

 num ciscuit ands
 28.5

 Fuse
 nak ckt-skk(*)
 40
HZTEST 3103



C. Duct Systems, Chases, and Vents

Comments:

C.1. Could not fully inspect vents. Limited attic access and visibility.

TrussWorthy Proper National Property Ins	rty Inspections, Inc. dba pections		2400 Jack	son Street, Gary, T〉
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				
		With the second secon		
	IV.	PLUMBING SYSTEM		
	A. Plumbing Supply, D	istribution System and F	ixtures	
	Location of Water Mete Location of Main Wate Comments:	er: Front of home, Left s r Supply Valve: Front of	ide home, Left side	
	A.1. Static Water Pres	ssure Reading (PSI): 60		

Water meter and shutoff

Water meter and shutoff

D=Deficient I=Inspected NI=Not Inspected NP=Not Present NI NP D Propane tank. Back yard Water pressure B. Drains, Wastes, and Vents Comments: B.1. Could not fully inspect vents due to accessibility constraints. May consider periodic sewer scan to validate drain integrity, laundry stand pipes and flows. C. Water Heating Equipment Energy Source: Water heaters are electric, located in garage, hall closet Capacity: 55 gallons. TPR valve was not jogged nor tested. Comments:



Water heater 1. Garage. 2011

Water heater 1 label

Х

Х




TrussWorthy Property Inspections, Inc. dba National Property Inspections	a	2400 Jackson Street, Gary, T
I=Inspected NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D		
X B. Food Waste Dispos	ers	
Comments:		
X C. Range Hood and Ex	xhaust Systems	
Comments:		
REI 7-5 (05/4/2015)		Page 21 of 30


X



REI 7-5 (05/4/2015)



TrussWorthy Property Inspections, Inc. dba National Property Inspections		2400 Jackson Street, Gary, TX
I=Inspected NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D		
x And	<image/> <caption></caption>	
X I. Other	Dijerexiladet	
Materials: Comments:		
REI 7-5 (05/4/2015)		Page 24 of 30
1 = 1 = 0 (00 + 1/20 = 10)		1 age 24 01 30



12 zone system

Controller wires

ussWorthy Prop ional Property I	perty Inspections, Inc. db nspections	a	2400 Jackson Street, Gary, ٦
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D)		
		Sample zone	
	B. Swimming Pools, S	pas, Hot Tubs, and Equ	lipment
	Comments:		
	pool, be self-closing, s	ot meet current safety st self-latching. This is a sa s. SOME debris present	tandards: must open away from afety issue. Filter gauge not legible.
	B.2. Some mineral de areas. Cosmetic.	posits present. MONITC	OR. Mortar separation in some
Entry gates do must open awa	not meet current safety s ay from pool, be self-clos latching	tandards: ing, self-	Filter gauge not legible

REI 7-5 (05/4/2015)

K

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D



Missing valve handles



Some mineral deposits present, spa spill over. MONITOR



Mortar separation in some areas. Cosmetic.



Pool and fountain

TrussWorthy Property Inspections, Inc. dba National Property Inspections


I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D



Pool heater

Sand filter

RATE

SAND

R O HIGH


THE REPORT OF ANY AND A DESCRIPTION OF A

Page 28 of 30

s

F

FILTER



Skimmer

Drains

Report Summary

STRUCTURAL SY	YSTEMS			
Page 3 Item: A	Foundations	A.2. Exposed foundation support members.		
Page 8 Item: E	Walls (Interior and Exterior)	E.1. Exterior: sealant, mortar separation. Cosmetic. Function of age. MONITOR		
		E.2. Interior: material separation. Cosmetic.		
Page 9 Item: F	Ceilings and Floors	F.2. Cracked tiles. MINOR.		
Page 11 Item: H	Windows	H.1. Cracked glass. Rusted <u>intel</u> s on some windows, not painted.		
ELECTRICAL SY	STEMS			
Page 15 Item: B	Branch Circuits, Connected Devices, and Fixtures	B.1. Missing switch cover.		
HVAC	HVAC			
Page 16 Item: B	Cooling Equipment	B.2. Missing dead front cover.		
PLUMBING SYST	[EM			
Page 20 Item: D	Hydro-Massage Therapy Equipment	D.1. Spa did not operate at time of inspection. Does not appear to have power.		
OPTIONAL SYSTEMS				
Page 26 Item: B	Swimming Pools, Spas, Hot Tubs, and Equipment	B.1. Entry gates do not meet current safety standards: must open away from pool, be self-closing, self-latching. This is a safety issue. Filter gauge not legible. Missing valve handles. SOME debris present.		
		B.2. Some mineral deposits present. MONITOR. Mortar separation in some areas. Cosmetic.		